

Survey of Subdivisions Of T, 39 1/2 N., R. 21 E.

Chains.

No timber.

North on random line bet. secs. 22 and 23.

37.40 Intersect the N. bdy. at a point 6lks. W. of the cor. of secs. 22, 23, 34 and 35.

Thence,

S. 0° 06' W. on true line bet. secs. 22 and 23.

36.70 Ravine, course N. 60° E.

37.40 The cor. of secs. 22, 23, 26 and 27.


Land, rolling, general drainage to the NE.

Soil, sandy gravelly clay loam, medium depth, covered with scattering lava rocks.

Scant growth of sage, good growth of bunch grass.

No timber.

From cor. of secs. 3, 4, 33 and 34 on the S. bdy., which is an iron post, 3 ft. long 3 ins. dia., showing 12 ins. above ground; marked and witnessed as described by the surveyor general. I change the marks on the brass cap to read as follows:




N0° 02' W. on true line bet. secs. 33 and 34.

Over broken land. Asc. gradual S. slope.

13.50 Top of low ridge, bears E. and W.; continue to asc.

40.00 Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for 1/4 sec. cor., with brass cap mkd.;



and raise a mound of stone, 2 ft. base, 1 1/2 ft. high, W. of cor.

50.00 Ridge, 160ft. above sec. cor., bears E. and W.; desc.