

Survey of the Subdivisions of T. 39 $\frac{1}{2}$  N., R. 21 E.

Chains

Scant growth of sage and bunch grass.

No timber.

From the cor. of secs. 5, 6, 31 and 32, on the S. bdy., which is an iron post, 3 ft. long, 3 ins. dia., showing 12 ins. above ground; marked and witnessed as described by the surveyor general. I change the marks on the brass cap to read as follows:

T39 $\frac{1}{2}$ N	R21E
S31	S32
S6	S5
T39N	R21E
1914	

N. 0° 04' W. on true line bet. secs. 31 and 32.

Over broken land. Asc. Abrupt S. slope.

40.00 Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.;

$\frac{1}{4}$	
S31	S32
1917	

and raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, W. of cor.

45.40 Top of mountain, 640 ft. above sec. cor., bears N. 60° W. and E.; desc. N. slope over bench and NE. slope semi abruptly 530 ft. to sec. cor.

78.00 Top of low spur, projecting NE.

80.00 Set an iron post, 3 ft. long, 2 ins. dia., 24 ins. in the ground, for cor. of secs. 29, 30, 31 and 32, with brass cap mkd.;

T39 $\frac{1}{2}$ N	R21E
S30	S29
S31	S32
1917	

and raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, W. of cor.

Land, mountainous, exposure to S. and NE.

Soil, heavy clay loam, very rocky, some exposed ledges,