

EXAMINATION FOR OBLITERATION

10

Tps. 15 & 16 S., R. 56 E. & T. 16 S., R. 56 E.

Marked for closing cor. of secs. 2 & 3 of T. 17 S., R. 56 E.

A limestone 10x11x6 ins. firmly set in a stone mound, with 4 grooves scratched on W. face, 2 grooves scratched on E. and CC scratched on N. faces, not witnessed.

At a point 39.65 chs. S. 89° 23' E. of S.C. of secs. 34 & 35, T. 16 S., R. 56 E., I find,

Marked for S.C. $\frac{1}{4}$ on S. bdy. of secs. 35,

A limestone 8 x 8 x 5 ins. loosely set in an earth mound, dimly marked $\frac{1}{4}$ on N. face, trace of a pit south, no other accessories.

These corners show plainly that the "4th. Standard Parallel South" is monumented on two different lines upon the ground for the south boundary of T. 16 S., R. 56 E. and that the two lines are about $\frac{1}{2}$ mile apart in northing and southing. The north one fits approximately with the Woods survey of 1881 in T. 16 S., R. 56 E. while the south line fits approximately with the "Ruby Valley Guide Meridian" as found monumented on the ground, and with closing cors. monumented and marked upon it.

The following is a description of the corners found monumented on the "Ruby Valley Guide Meridian", between T. 16 S., Rs. 55 & 56 E., Mt. D. Base & Mer.

S. C. of T. 16 S., R. 55 & 56 E.

A limestone 17x12x6 ins. above mound, firmly set in a stone mound, plainly marked 6 notches on N., S., E. & W. edges, not witnessed.

The $\frac{1}{4}$ cor. bet. secs. 31 & 36

A limestone 12x12x9 ins. firmly set in a stone mound, plainly marked $\frac{1}{4}$ on W face, not witnessed.

The $\frac{1}{4}$ cor. bet. secs. 25 & 30

A limestone 18x12x10 ins. loosely set in an earth mound, plainly marked $\frac{1}{4}$ on W face, not witnessed.