Tps. 15 & 16 S., R. 56 E., & T. 16 S., R. 55 E.

A limestone 12x12x8 ins. loosely set in an earth mound, plainly marked, 4 grooves on E. face, 3 notches on ME. edge, 1 plain and 5 dim notches on NW. edge, 6 dim notches on W. edge, and 6 dim notches on S. edge, with traces of three pits, NE, SE & SW. of cor.

The cor. of secs. 25, 30, 31 & 36

A limestone 6x6x5 ins. above ground, firmly set in an earth mound, plainly marked 5 notches on N. and 1 notch on S. edges, plain traces of 3 pits, SE., SW. & NW. of cor.

The \(\frac{1}{4}\) cor. bet. secs. 25 & 30.

A hard sandstone 10x4x3 ins. above ground, surrounded with stones, plainly marked $\frac{1}{4}$ on W. face, not witnessed.

The cor. of secs. 19, 24, 25 & 30.

A limestone 8x8x5 ins. above stone mound, firmly set in a stone mound, plainly marked 4 notches on N. and 2 notches on S. edges, not witnessed.

The following is a description of corners found monumented on the ground, on the "4th Standard Parallel South" in Range 55 E. which forms the south bdy. of

T. 16 S., R. 55 E.

The S C $\frac{1}{4}$ on S. bdy. sec. 36.

A limestone 20x10x8 ins. above ground, loosely set in a small earth mound, plainly marked $\frac{1}{4}$ on N. face, not witnessed.

S. C. of secs. 35 & 36.

A quartzite stone 13x9x8 ins. above ground, loosely set in a small earth mound plainly marked 5 notches on E. 1 notch on W. and SC. on NW faces, not witnessed.

At a point 1.90 chs. east of the above described SC. of secs. 35 and 36, I find,

Marked for CC of secs. 1 and 2, of T. 17 S., R. 55 E.