

## Chains

119.65 Fall 24 lks. S. of the original  $\frac{1}{4}$  sec. cor., bet. secs. 28 and 35 hereinafter described.

159.55 Fall 28 lks. S. of the original cor. of secs. 2, 3, 34 and 35 hereinafter described.

199.52 Fall 29 lks. S. of the original  $\frac{1}{2}$  sec. cor., bet. secs. 34 and 34 hereinafter described.

225.92 No trace of original meander corner found after diligent search.

---

Survey of the South boundary of T. 11 N., R. 29 E.

---

The Standard cor. of Ts. 11 N., Rs. 29 and 30 East, I move East, 123.34 chs. to true position, and establish as follows;

Set an iron post, 3 ft. long, 3 ins. in dia., 24 ins. in ground, for standard cor. of Ts. 11 N., Rs. 29 and 30 East, with brass cap marked,

S C	
T 11 N	
R 29 E	R 30 E
S 36	S 31

1918 ; dig pits,  
30x24x12 ins. crosswise on each line, E. and W., 4 ft. and North of cor. 8ft. dist.

---

Survey of the 2nd Standard Parallel N. thru Range 29 E.

---

From the standard corner of Ts. 11 N., Rs. 29 and 30 East, previously described,

West, on the 2nd Standard Parallel North, on the south boundary of sec. 36.