

## Survey of the meanders of T. 111 N., R. 29 E.

## Chains

From the Standard meander cor. of sec. 35, on the south boundary of the township, Along rocky shore,

N.  $12\frac{1}{2}^{\circ}$ W., 5.00 chs.,

N.  $12\frac{1}{2}^{\circ}$ W., 35.00 chs.,

N.  $13^{\circ}$ W., 42.30 chs., to the meander corner of fractional secs. 26 and 35.; previously described.

Land, gentle slope to lake.

Soil, sand and gravel.

Undergrowth, greasewood and low sage.

Thence, in sec. 26.

Over sandy gravelly shore,

N.  $8^{\circ}35'$ W., 46.10 chs. to the meander cor. of fractional secs. 27 and 26.

Land, gentle slope to lake.

Soil, sand and gravel.

Undergrowth, greasewood back from water line.

Thence, in sec. 27,

N.  $35\frac{1}{2}^{\circ}$ W., 22.50 chs.,

N.  $36\frac{3}{4}^{\circ}$ W., 20.00 chs., to the fractional meander cor. of secs. 22 and 27.

Land, gently sloping to the lake.

Soil, sand and gravel.

Undergrowth, greasewood.

Thence, in sec. 22,

Along a rocky, sandy shore,

N.  $30\frac{3}{4}^{\circ}$ W., 82.10 chs.,

N.  $22\frac{3}{4}^{\circ}$ W., 10.00 chs., to the meander corner of fractional secs. 15 and 22.

Land, gently sloping to the lake.

Soil, sandy and gravelly.

Undergrowth, greasewood and sage.