

Retracement of South bdy. of sec. 36, T. 37 N., R. 30 E.  
and survey of a portion of the North bdy. of sec. 6, of T. 36 N., R. 31 E.

Chains.

From the SE. cor. of T. 37 N., R. 30 E., previously described,  
West, on a retracement of the S. bdy. of sec. 36, T. 37 N.,  
R. 30 E.

40.00 Make diligent search but find no trace of the  $\frac{1}{4}$  sec. cor.

80.43 Fall 9 lks. N. of the old cor. of secs. 1, 2, 35 and 36 on the  
S. bdy. of T., which is a trap rock 16x5x4 ins.; marked  
as described by the surveyor general.

I return to the SE. cor. of T. 37 N., R. 30 E., previously  
described.

Thence, S. 89° 56' W., on a true line on the North bdy. of sec.  
6, T. 36 N., R. 31 E.  
Desc. 20 ft. over W. slope.

2.00 Shallow draw, course SW. Asc. 190 ft. over E. slope.

16.00 Ridge, bears N. and S. Desc. 220 ft. over broken W. slope.

32.40 Gulch, course S. 20° W. Asc. 10 ft. over E. slope.

32.73 The cor. of T. 36 N., Rs. 30 and 31 E., previously described.  
Land hilly.

Soil, 5 chs. on East end of line, deep fine sand with clay  
subsoil; balance of line clay with trap rock imbedded  
and lying on the surface of the ridges.

No timber except near West end of line.

Undergrowth, sage and shadscale.