

Independent Resurvey, South Boundary, T. 10 S., R. 69 E.

Chains

T10S R69E

S31 | S32

S6 | S5

T11S

1934

Cross (X) mkd. on solid rock at base of post.

Land, rolling.

Soil, sandy clay; 3rd rate.

Undergrowth, buckbrush, creosote, cacti, mountain rush;
bunch grass, and sand grass.

No timber.

N. 89°58' W., bet. secs. 6 and 31.

Over rolling country, through medium dense undergrowth;
asc. 70 ft. on SE. slope.13.50 On S. slope round knoll, summit to N.; desc. slight SW.
slope.

24.70 Road (Glendale to Pioche), bears N. and S.; asc. 20 ft.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 18 ins. in
the ground to solid rock, in a mound of stone, for $\frac{1}{4}$ sec.
cor., with brass cap mkd.

S31

 $\frac{1}{4}$

S6

1934

Cross (X) mkd. on solid rock at base of post.

Continue over rolling country; asc. 75 ft. on a general
NE. slope to Tp. cor.

55.60 Draw, course NE.

75.90 Draw, course NE.

78.91 The corner of Tps. 10 and 11 S., Rs. 68 and 69 E.

Land, rolling.

Soil, sandy clay.

Undergrowth, buckbrush, creosote, cacti, mountain rush;
bunch grass and sand grass.

No timber.

SURVEY OF THE SOUTH BOUNDARY OF T. 10 S., R. 68 E.

Preliminary surveys having determined that a line connecting the cor. of Tps. 10 and 11 S., Rs. 67 and 68 E. with the cor. of Tps. 10 and 11 S., Rs. 68 and 69 E. will not be within limits to serve as a control boundary, at the cor. of Tps. 10 and 11 S., Rs. 68 and 69 E., I deflect an angle of 90°00' to the west from a flag set at the cor. of secs. 1, 6, 7, and 12, on the E. bdy. of T.