

RESURVEY OF 9TH STANDARD PARALLEL NORTH IN R. 58 E.

Chains

SC  
T46NR58E  
S31 | S32  
-----  
1936

From the corner point the original cor., a granite stone, 16x10x8 ins., firmly set, properly marked and witnessed as described in the official record, bears 8.64 chs. N.86°49'W.; I destroy all evidence of this cor.

Land, rough and broken mountain slopes, general SE. exposure and drainage.

Soil, shallow gravelly to rocky loam, 3rd rate.

Timber, pine, fir and mahogany; undergrowth, sagebrush, mountain rush and weeds. Native grass.

Fair grazing.

West, along the south boundary of sec. 31, on a transit line describing the tangent and which bears S.89°56.1'W.

Over mountainous land, through medium dense timber and a scant undergrowth; asc. 230 ft. along a SE. slope.

8.40 Ridge, bears N. and S.25°E., divide between Pine and Bear Creeks; desc. 190 ft. along a NW. slope.

18.20 Unused road in the bottom of a depression draining N.; asc. 270 ft. along a NE. slope.

37.30 Top of ascent sloping N.; desc. 30 ft. along a NW. slope.

40.00 North 27 lks. from the tangent,

Set an iron post, 3 ft. long, 1 in. diam., 20 ins. in the ground to solid rock, and in a mound of stone, for standard  $\frac{1}{4}$  sec. cor., with brass cap mkd.

SC  
 $\frac{1}{4}$ S31  
-----  
1936

from which,

A pine, 5 ins. diam., bears N.78 $\frac{1}{4}$ °E., 33 lks. dist., mkd.  $\frac{1}{4}$  S31 SC BT.

A pine, 5 ins. diam., bears N.68°W., 57 lks. dist., mkd.  $\frac{1}{4}$  S31 SC BT.

No trace of the original cor. could be found.

Desc. 80 ft. along a NW. slope to the depression at the 55.60 ch. pt.

52.90 Old road, bears N. and S.

55.60 Bottom of depression draining N.; asc. 90 ft. along an E. slope.

61.40 Ridge, bears N. and SE., divide between Bear and Coon Creeks; desc. 470 ft. over a W. slope to the wash.