

## RESURVEY OF 9TH STANDARD PARALLEL NORTH IN R. 57 E.

Chains

An aspen, 4 ins. diam., bears N.62°E., 69 lks. dist.,  
mkd.  $\frac{1}{4}$  S36 SC BT.

No other suitable tree available for marking.

No trace of the original cor. could be found.

Land, steeply sloping mountain side, W. exposure and  
drainage.

Soil, sandy to gravelly loam, 2nd rate.

Timber, scattered aspen and fir; undergrowth, sagebrush,  
mountain rush and weeds. Native grasses.

Good grazing.

## EAST BOUNDARY OF T. 45 N., R. 58 E.

Beginning at the cor. of Townships 44 and 45 North, Range  
58 East, an iron post, 3 ins. diam., firmly set in the  
ground, properly mkd. and witnessed as described in the  
official record, thence,

North, along the E. bdy. of sec. 36.

Over mountainous land, through scattering timber and a  
medium dense undergrowth; asc. 360 ft. along a SW. slope  
to the spur.

9.25 Small draw, drains SW.; continue ascent.

11.35 Spur, slopes SW.; asc. 560 ft. along a SW. slope.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 32 ins. in the  
ground, for  $\frac{1}{4}$  sec. cor. of sec. 36 only, with brass cap  
mkd.

$\frac{1}{4}$ S36

1935

from which,

A fir, 22 ins. diam., bears S.81 $\frac{1}{2}$ °W., 14 lks. dist.,  
mkd.  $\frac{1}{4}$  S36 BT.

No other suitable tree available for marking.

Asc. 1090 ft. over SW. and S. slopes.

75.78 Flag on high, rocky ridge bearing E. and S.80°W., divide  
between the east and west forks of Mary's River.

76.16 Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the  
ground to solid rock, with a trachyte stone, 7x6x4 ins.,  
mkd. X deposited at the base, and in a mound of stone,  
for witness cor. of secs. 25 and 36, T. 45 N., R. 58 E.,  
only, with brass cap mkd.

WC

T45N T45N

S25

S30

S36

R58E R59E

1935

Desc. 70 ft. along a NW. slope.