

SUBDIVISION OF T. 45 N., R. 58 E.

Chains

Soil, gravelly to rocky loam, 3rd rate.
 Timber, pine, fir and aspen; undergrowth, sagebrush and
 weeds. Native grasses.
 Good grazing.

N.0°02'W. on true line between secs. 3 and 4.

Over mountainous land; through scattering timber and a
 dense undergrowth; desc. 200 ft. over a broken NW. slope
 along the east side of Fox Creek.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the
 ground to solid rock, with a granite stone, 6x3x2 ins.,
 mkd. X, deposited at the base, and in a mound of stone,
 for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
 S4 | S3
 1936

Continue along a broken slope; desc. 90 ft. to the
 closing cor.

47.10 Intersect the 9th Standard Parallel North.

Set an iron post, 3 ft. long, 2 ins. diam., 6 ins. in the
 ground to solid rock, with a granite stone, 5x4x2 ins.,
 mkd. X deposited at the base, and in a mound of stone,
 for closing cor. of secs. 3 and 4, with brass cap mkd.

T46NR58E
 S33
 S4 | S3
 T45NR58E
 CC
 1936

From point of intersection, the standard $\frac{1}{4}$ sec. cor. on
 S. bdy. of sec. 33, T. 46 N., R. 58 E., heretofore
 described, bears West, 9.80 chs. dist.

Land, broken slopes bordering the edge of Fox Creek,
 exposure and drainage NW.
 Soil, sandy to gravelly loam, 2nd rate.
 Timber, scattered aspen and fir; undergrowth, sagebrush
 and weeds. Native grasses.
 Good grazing.

Thence, from the cor. of secs. 32 and 33, on the S. bdy.
 of the tp., an iron post, 2 ins. diam., firmly set,
 properly mkd. and witnessed as described in the official
 record.

N.0°03'W. between secs. 32 and 33.

Over mountainous land, through scattering timber and a
 dense undergrowth; asc. 150 ft. along a SW. slope.

15.90 Ridge, bears NE. and SW., divide between 76 Creek and
 Mary's River; desc. 350 ft. along a NW. slope.