

INDEPENDENT RESURVEY OF THE 9TH STAN. PAR. N.,
THROUGH RANGE 59 E.

Chains

through scattering pine, fir and mahogany timber with an undergrowth of sagebrush.

3.37 After diligent search no trace could be found of the original standard cor. of secs. 32 and 33.

11.50 Shallow draw, drains NW.

13.60 Point of low spur, slopes N.21°W.

24.40 Trail, bears N. and S.

25.90 E. fork of Jarbidge River, 17 lks. wide, 10 ins. deep, flows N.10°E., asc. 960 ft. over an E. slope.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 6 ins. in the ground, to bed rock, with a granite stone 4x4x4 ins. mkd. X, deposited at base, and in a mound of stone to top, for the standard $\frac{1}{4}$ sec. cor., with brass cap mkd.

S C

$\frac{1}{4}$ S32
1936

43.37 After diligent search no trace could be found of the standard $\frac{1}{4}$ sec. cor.

50.60 Spur, slopes NE., desc. 410 ft. over a W. slope.

62.00 Trail, bears N.20°W. and S.20°E.

65.50 Cougar Creek, 12 lks. wide, 6 ins. deep, flows N., asc. 370 ft. over an E. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 32 ins. in the ground, for the standard cor. of secs. 31 and 32, with brass cap marked

S C

T46N R59E

S31 | S32

1936

from which

A pine, 6 ins. diam., bears N.43 $\frac{1}{2}$ °E., 132 lks. dist., mkd. T46N R59E S32 S C BT.

A mahogany, 5 ins. diam., bears N.30°W., 115 lks. dist., mkd. T46N R59E S31 S C BT.

Land, rough mountainous.

Soil, fine sandy clay, with rock outcroppings, 3rd rate.

Timber, pine, fir, aspen and mahogany; undergrowth, sagebrush, buckbrush and chokecherry.

Grazing, poor.

West, along the S. bdy. of sec. 31.

Asc. 720 ft. over rough mountainous land, on an E. slope, through scattering pine, fir and mahogany, with an undergrowth of sagebrush, buckbrush and chokecherry.

3.37 After diligent search no trace could be found of the original standard cor. of secs. 31 and 32.

16.40 Ridge, bears N. and S., over broken top of ridge.