

Chains

$$\begin{array}{r} \frac{1}{2} \\ \hline S \ 31 \\ S \ 6 \\ 1919 \end{array}$$

and raise mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, N. of the cor.

54.80 Draw, drains S. Asc. 32 ft.

59.00 Spur, slopes SE. Desc. 18 ft.

61.50 Draw, drains SE. Thence over broken land.

69.10 Spur, projects N.

74.50 Draw, drains S.

78.34 Set iron post, 3 ft. long, 3 ins. in diam., 24 ins. in the ground, for the cor. of Ts. 5 and 6 S., Rs. 65 and 66 E., with brass cap marked

$$\begin{array}{r} T \ 5 \ S \\ R \ 65 \ E \ R \ 66 \ E \\ S \ 36 \ S \ 31 \\ \hline S \ 1 \ S \ 6 \\ T \ 6 \ S \\ 1919 \end{array}$$

and raise mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, S. of the cor.

Land, rolling mountains ; Soil, rocky, 3rd. rate; Timber, cedar, pinon pine, and juniper; Undergrowth, sage brush, service berry, and live oak, and mountain rush.

From the cor. of Ts. 6 and 7 S., Rs. 66 and 67 E., which is an iron post, 3 ins. in diam., showing 12 ins. above ground, marked and witnessed as described by the Surveyor General.

West, on the S. bdy. of sec. 36.

Over rocky broken mountains, covered with, buck brush, joshua, shadscale, sage, and soap weed.

Desc. 137 ft., over NW. slope.

3.10 Top of spur, project NW. Continue desc. over W. slope.

12.90 East rim of Meadow Valley wash, as it is impossible to chain further on account of impassable cliffs, both on the east and west side of the canyon, triangulate as follows: