

## Meanders of Walker Lake through T. 9 N., R. 29 E.

CHAINS From the Meander Cor. of secs. 5 and 32, on the N. bdy.  
of T. 9 N., R. 29 E.

Thence with meanders thru sec. 5.

Along high water line of Walker Lake, over broken, rocky  
cliffs.

S.  $61^{\circ} 30'$  E. 0.87 chs.  
S.  $35^{\circ} 30'$  E. 12.00 "  
S.  $18^{\circ} 45'$  E. 19.67 "  
S.  $35^{\circ} 45'$  E. 4.20 "  
S.  $20^{\circ} 45'$  E. 4.87 "  
S.  $29^{\circ} 15'$  E. 1.17 "  
S.  $12^{\circ} 15'$  W. 2.06 "  
S.  $20^{\circ} 15'$  E. 3.16 "  
S.  $0^{\circ} 45'$  E. 23.37 "  
S.  $48^{\circ} 00'$  E. 8.20 " To M. C. for secs. 5 and 8.  
S.  $15^{\circ} 15'$  W. 6.51 "  
S.  $18^{\circ} 30'$  W. 1.79 " To the M. C. of secs. 5 and 8.

Land, mountainous; Soil, rocky, 4th rate; Timber, none;  
Undergrowth, none.

Thence with meanders thru sec. 8.

Along high water line of Walker Lake, over cliffs.

S.  $11^{\circ} 45'$  E. 23.50 chs. Leaving cliffs, thence along  
level shore line.  
S.  $65^{\circ} 49'$  E. 32.26 " To M. C. for secs. 8 and 9.

Land mountainous and level; Soil, rocky to gravelly; 3rd  
and 4th rate; Timber, none; Undergrowth, none.

Thence with meanders thru sec. 9.

Along high water line of Walker Lake, over level land.

S.  $68^{\circ} 00'$  E. 2.10 chs.  
S.  $29^{\circ} 15'$  E. 2.96 chs. Along shore line.  
S.  $39^{\circ} 45'$  E. 6.80 "  
S.  $14^{\circ} 30'$  E. 7.70 "  
S.  $10^{\circ} 15'$  E. 14.20 "  
S.  $9^{\circ} 57'$  W. 13.62 " To M. C. for secs. 9 and 16.

Land, level; Soil, gravelly; 3rd rate; Timber, none;  
Undergrowth, none.

Thence with meanders thru sec. 16.

Along high water line of Walker Lake, over level land.

S.  $26^{\circ} 30'$  E. 18.80 chs.  
S.  $3^{\circ} 00'$  E. 3.10 " Along shore line.  
S.  $8^{\circ} 00'$  W. 13.80 "  
S.  $36^{\circ} 30'$  E. 7.90 " Along shore line.  
S.  $52^{\circ} 30'$  E. 25.00 "  
S.  $8^{\circ} 00'$  W. 7.70 "  
S.  $13^{\circ} 45'$  W. 10.00 "  
S.  $9^{\circ} 05'$  E. 7.51 " To M. C. for secs. 16 and 21.