Resurvey of a portion of the S. Bdy. of T. 13 N., R. 28 E.

The original cor. of secs. 1, 2, 35 and 36, on S. Bdy.

of T. 13 N., R. 28 E., I find to be a redwood post,

14 ins. above the ground,  $4\frac{1}{2}$  ins sq., firmly set, and

markings nearly obliterated. Therefore alongside.

Set an iron post, 3 ft. long, 2 ins. dia., 24 ins. in

the ground, for cor. of secs. 1, 2, 35 and 36, with brass cap mkd.

T13N R28E S35 S36 S 2 S 1 T12N 1922

and raise a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

Thence

East, on a true line, bet. secs. 1 and 36.

Over nearly level bench land, through scattering undergrowth.

- 8.20 Main road, from Schurz, to Walker Lake, bears N. 20° W., and S. 20° E.
- 19.00 Head of dry wash, course NE.
- 22.40 Road, bears NW. and SE.
- 27.50 Leave bench land, bears N. 20° W. and S. 20° E., desc. 50 ft. over abrupt bluff.
- 28.80 Dry ditch, 8 lks. wide, 2 ft. deep, course S. 20° E.,
- 30.00 Base of bluff, enter nearly level bottom land, bears
  . N. 20° W. and S. 20° E.

Enter cottonwood timber and willows, bears N. 20° W., and S. 20° E.

Intersect the original  $\frac{1}{4}$  cor. of secs. 1 and 36, which I find to be a greatly decayed post, with marks almost obliterated. Alongside this cor.

Set an iron post, 3 ft. long, 1 in. dia., 26 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

1 S 36 4 S I 1922

From which

A Cottonwood tree,  $2\frac{1}{2}$  ft. in dia., bears N. 13° W., 81