


Dependent Resurvey of the N. boundary of T.42 N., R.51 E.

Chains From the  $\frac{1}{4}$  sec. cor. of secs. 1 and 36, which is a granite stone, 14 x 8 x 8 ins. surrounded by mound of stone with  $\frac{1}{4}$  marked on the S. face. I reconstruct as follows: Along side, set iron post, 3 ft. long, 1 in. in diam., 10 ins. in the ground, surrounded by mound of stone, 3 ft. base, 2 ft. high, for the  $\frac{1}{4}$  sec. cor., with brass cap marked




and raise mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, N. of the cor.

N. 89° 48' W., on true line, on the N. boundary of sec. 1. Desc. 343 ft. over broken SW. slope. covered with sage brush.

39.53 The old cor. of sec. 1, 2, 35 and 36, which is a granite stone, 22 x 12 x 8 ins. surrounded by mound of stone, marked and witnessed as described by the Surveyor General. Mercer reconstructed this cor. the fall of 1918 while engaged in retracement on group 67.

On W. side set iron post, 3 ft. long, 2 ins. in diam., 10 ins. in the ground, surrounded by mound of stone, 3 ft. base, 2 ft. high, for the cor. of secs. 1, 2, 35 and 36, with brass cap marked



and raise mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, W. of the cor.

From this corner a large spring bears S. 70° W. Land, rolling; Soil, rocky, 3rd. rate; Timber, none; Undergrowth, sage brush.

-----  
From the reconstructed cor. of secs. 1, 2, 35 and 36. S. 89° 45' W., on true line, on N. boundary of sec. 2.

23.20 Desc. 343 ft. over SW. slope covered with sage brush.

23.20 Telephone line, bears NW. and SE.