

INVESTIGATION SURVEY, GROUP 69, NEVADA.

Std. cor. of secs. 33 and 34. Granite stone, 24x14x8 ins. in a mound of stone, mkd. "SC" on N. face, 2 grooves on E. face, and 4 grooves on W. face.

Sbd. $\frac{1}{4}$ Sec. 34. Granite stone, 10x12x18 ins. in a mound of stone, mkd. " $\frac{1}{4}$ SC" on N. face.

Cor. of sec. 34. Granite stone, 12x10x8 ins. in a mound of stone, mkd. and witnessed as described by the surveyor general.

Std. cor. of Secs. 34 and 35. Granite stone, 10x12x15 ins. in a mound of stone, mkd. and witnessed as described by the surveyor general.

T. 31 N., R. 34 E.

C.C. of secs. 1 and 2. Granite stone, 6x12x14 ins. in mound of stone, mkd. "CC" on S. face, 1 groove E. and 5 grooves W.

$\frac{1}{4}$ cor. sec. 2. Granite stone, 10x12x15 ins. in mound of stone, mkd. and witnessed as described by the surveyor general.

C.C. of secs. 2 and 3. Limestone, 5x10x14 ins. in a mound of stone, mkd. "CC" on S. face, 2 notches E. and 4 notches W.

Cor. of secs. 2, 3, 10 and 11. Granite stone, 5x10x12 ins. in a mound of stone, mkd. 2 notches on E. and 5 notches on S.

C.C. of secs. 3 and 4. Limestone, 2x10x20 ins. in a mound of stone, mkd. "CC" on S. face, 3 notches on E. and W. edges.

Cor. of secs. 3, 4, 9 and 10. An old mound of stone on very steep hillside; mound slightly scattered and no trace of marked stone. Corner stone has evidently rolled down slope.

C.C. of secs. 5 and 6. Granite stone, 6x8x14 ins. in a mound of stone, "CC" on S. face, 1 groove W. and 5 grooves E.

Cor. of secs. 5, 6, 7, and 8. Granite stone, 6x7x14