

Subdivision of T. 45 N., R. 53 E.

CHAINS

- 60.20 Old road, bears N.20°E. and S.20°W.
Desc. over broken NE. slope.
- 70.90 Dry wash, 100 ft. below $\frac{1}{4}$ sec. cor., drains E.
Asc. over broken S. slope, 60 ft. to spur.
- 73.70 Wire fence, bears N.80°W. and S.80°E.
- 75.80 Top of isolated, grey granite boulder, 8x10x10 ft. high.
- 79.85 NE. break of small spur, projects E. 5 chs.
Desc. 100 ft. over abrupt N. slope.
- 82.70 Base of N. slope and old road, bears NW. and SE.
Thru dense thicket of willow and briar undergrowth
over level land.
- 84.40 Leave dense undergrowth, enter cultivated field, bears
NW. and SE.
- 86.06 Intersect line 2-3 of H.E.S. No. 39. Point for Cor. No.
3, heretofore described, bears N.24°W., 15.84 chs.
dist. Cor. No. 2 bears S.24°E., 10.86 chs. distant.
- 99.71 Intersect Ninth Std. Par. N., West, 1.01 chs. from the
restored Std. $\frac{1}{4}$ sec. cor. of sec. 36, heretofore
described.
- At point of intersection,
Set an iron post, 3 ft. long, 2 ins. diam., 36 ins. in
the ground, for closing cor. of secs. 1 and 2, with
brass cap mkd:
- | | |
|-----------|------|
| T46N R53E | |
| S 36 | |
| S 2 | S 1 |
| T45N | R53E |
| CC | |
| 1921 | |
- Corner in center of cultivated field; impracticable
to erect mound of stone or dig pits for accessories.
Land, rolling and level. NE. exposure and drainage.
Soil, gravelly and rocky, shallow loam, 3rd rate on
slopes. Sandy gravelly loam, medium texture, 1st and
2nd rate on bottom lands.
Undergrowth, sagebrush, willows, briar, buck brush.
No timber. Good grazing.