

## Dependent Resurvey of the Nevada-Utah State Line.

## Chains.

- 53.75 Enter dense pinon pine and cedar timber, bears N.80° W. and S.80° E.
- 54.35 Dry wash, 190 ft. below spur, course N.80° W.
- 58.30 Top of spur, 75 ft. above wash, projects W.
- 62.30 Dry wash, 75 ft. below spur, course W.
- 68.40 Point of spur, 135 ft. above wash, projects S.75° W.
- 71.25 Intersect the 104th mile post, which is an iron post, 3 ins. in dia., properly marked and witnessed.
- Land, rough mountainous. Soil, rocky clay loam.
- Undergrowth, sage and scant growth of bunch grass.
- Timber, pinon pine, cedar and mahogany.

## Survey of the N. Bdy. of T.22 N., R.70 E.

- From the cor. of Ts.22 and 23 N., Rs. 69 and 70 E., which is an iron post, 3 ins. in dia., properly marked and witnessed.
- East on a true line, bet. secs. 6 and 31.
- Asc. S.W. slope over rough mountainous land, through dense pinon pine and cedar timber.
- 15.20 Top of rocky spur, 369 ft. above twp. cor., projects N.W.
- Desc. N.E. slope.
- 19.50 Dry wash, 101 ft. below spur, course N.W.
- Asc. N.W. slope.
- 27.50 Top of rocky spur, 165 ft. above wash, projects N.
- Desc. N.E. slope.
- 31.70 Dry wash, 99 ft. below spur, course N.W.
- Asc. S.W. slope.
- 36.60 Point of rocky spur, 79 ft. above wash, projects S.
- Desc. S.E. slope 10 ft. to
- 40.00 Dry wash, course W.
- Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in the ground, for the  $\frac{1}{4}$  sec. cor., with brass cap mkd.

S31

 $\frac{1}{4}$ 

S6

1922