

INDEPENDENT RESURVEY OF SUBDIVISIONS OF T.8 N., R.29 E.

CHAINS
59.75

Rose Creek, 240 ft. below spur, course E., 4 lks. wide,
8 ins. deep, good water, abrupt ascent of 770 ft. up
N. slope.

76.66

Ascend NE. slope 140 ft. to sec. cor.

82.80

The cor. of secs. 4, 5, 8 and 9.

Land mountainous; general drainage NE.

Soil, rocky.

Timber, pinon and cedar.

Undergrowth, sagebrush and willow.

MEANDERS OF WALKER LAKE IN T.8 N., R.29 E.

I begin at the meander. cor. for secs. 2 and 35, Tps. 88
and 9 N., R. 29 E., which is a 1 in. iron post, firmly
set in a mound of stone, and marked and witnessed as
described by the Surveyor General.

Thence with meanders in sec. 2

Along beach of conglomerate outcropping and boulders.

S. 0° 12' W. 22.37 chs.

S. 61° E. 15.00 chs. To the meander. cor. of fracl.

secs. 1 and 2, heretofore described.

Land level.

Soil, gravelly sand.

Timber, none.

Undergrowth, sagebrush and willow.

Thence in sec. 1.

Along beach of conglomerate formation and boulders.

S. 61° E. 7.78 chs.

S. 53½° E. 12.30 chs.

S. 37° E. 12.00 chs.

S. 25½° E. 10.00 chs.

South 22.90 chs. To the meander cor. of fracl.

secs. 1 and 12, heretofore described.

Land level.

Soil, gravelly sand.

Timber, none.

Undergrowth, sagebrush and willow.