

## INDEPENDENT RESURVEY OF SUBDIVISIONS OF T. 8 N., R. 30 E.

## CHAINS

78.44

The cor. of secs. 2 and 3, on limiting outboundary.

Land, level.

Soil, sandy

Timber, none.

Undergrowth, sage, greasewood and salt grass.

MEANDERS OF WALKER LAKE IN T. 8 N., R. 30 E.

I begin at the meander cor. for fracl. secs. 3 and 34, Tps. 8 and 9 N., R. 30 E., which is a 1 in. iron post, 8 ins. above ground, marked and witnessed as described by the Surveyor General.

Thence with meanders in sec. 3

Along level sandy beach.

S. 31° 05' W. 42.89 chs.

S. 26° 45' W. 28.70 chs. To the meander cor. of fracl.

secs. 3 and 4, hereinbefore described.

Land, level.

Soil, sandy.

Timber, none.

Undergrowth, none.

Thence, in sec. 4.

S. 40° 55' W., 41.85 chs. To the meander cor. of fracl.

secs. 4 and 9, hereinbefore described.

Land, level.

Soil, sandy.

Timber, none.

Undergrowth, none.

Thence, in sec. 9

Along level, <sup>sandy</sup> beach.

S. 65° 45' W. 13.90 chs.

S. 65° 19' W. 43.91 chs. To the meander cor. of fracl.

secs. 8 and 9, hereinbefore described.

Land, level.

Soil, sandy.

Timber and undergrowth, none.