

Chains

with 4 ft. base, for angle point No. 4 of tract No. 37, with brass cap mkd.

TR 37 | S32
 AP 4 |
 T44N R30E
 1921

Thence angle point for cor. No. 1 being visible, I run North, on a true line, on E. Bdy. of Tract No. 37.

4.25 Intersect E. and W. line, bet. secs. 29 and 32, at a point 3.83 chs. S. 89° 48' W. of the $\frac{1}{4}$ cor. of secs. 29 and 32, which is an iron post, 1 in. diam., 10 ins. above the ground, firmly set, mkd. and witnessed as described by the surveyor general.

Thence continue on true line on E. Bdy. of tract No. 37. with measurement.

20.00 The cor. for angle point No. 1 of Tract No. 37, which is the point of beginning.

General Description.

The character of the land covered by tract No. 37 and the adjusted entries in secs. 19, 20 and 30, is rough mountainous. The soil is of a fine black damp sandy clay loam. The whole section is covered by a dense heavy growth of sagebrush and a fair growth of bunch grass. Pass Creek, traverses nearly through the center of tract No. 37 in an easterly direction. The other entered land which was conformed to the lines of the 1918 survey is also well watered by Big Creek and numerous smaller streams, which flow through same in an easterly direction. All of this land being used for grazing purposes.

Emil Voigt.
 U.S. Cadastral Engineer.