

## SURVEY OF A PORTION OF N. BDY. OF T. 20 N., R. 46 E.

## CHAINS

Land, rolling. Soil, rocky and gravelly loam.  
 Timber, none. Undergrowth, sagebrush and shadscale.  
 Fair grazing. General drainage, NW.

## SUBDIVISIONS T. 20 N., R. 46 E.

From the cor. of secs. 1, 2, 35 and 36, on S. bdy. of tp,  
 which is a 3 in. iron post, firmly set in the ground,  
 marked and witnessed as described by the Surveyor  
 General

N 0° 01' W., bet. secs. 35 and 36

Slight descent along NE. slope over rough mountainous  
 land

7.70 Asc. along steep rocky SE. to E. slope 245 ft. to

26.20 Ravine with water, 4 lks. wide, 6 ins. deep, course S 45°  
 E. Asc. steep rocky SW. slope 145 ft. to

40.00 On gentle SW. slope

Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the  
 ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd  
 $\frac{1}{4}$

S35 | S36

1924

Raise a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

Asc. along SW. slope 105 ft. to

48.30 Spur, projects SW. Desc. along moderate SE. slope  
 wide

63.20 Dry wash in ravine, 10 lks. / 6 ft. deep, heads about 20  
 chs. NE., drains S 45° W. Asc. steep rocky SE. slope  
 375 ft. over boulders to

80.00 On steep rocky S. slope

Set an iron post, 3 ft. long, 2 ins. dia., 12 ins. in the  
 ground to solid rock, in a mound of stone, for the cor.  
 of secs. 25, 26, 35 and 36, with brass cap mkd

T20N | R46E

S26 | S25

S35 | S36

1924

At base of post deposit a marked(x) stone, 2x2x4 ins.

Land, rough mountainous. Soil, rocky,  
 Timber, few pinon. Undergrowth, sagebrush.

Fair grazing. General drainage, SW.