


Survey of the East boundary of T. 25 N., R. 48 E.

Chains

Chains

brass cap mkd:



1922

Raise a mound of stone, 3 ft. base, 1 ft. high, W. of cor.

4.30

45.00 Spur, 30 ft. above $\frac{1}{4}$ sec. cor., projects W.

14.90

57.00 Draw, drains W., asc. gradual S. slope.

59.70 Wire fence, bears E. and W.

23.50

66.20 Spur ridge, 130 ft. above draw, projects S. of W. and NW. from E., desc. abrupt N. slope.

28.00


73.70 Main draw, 170 ft. below ridge, drains W., asc. S. slope.

35.25

75.25 The point subsequently determined for the closing corner of Ts. 24 and 25 N., R. 48 $\frac{1}{2}$ E.,

Set an iron post, 3 ft. long, 3 ins. diam., 30 ins. in the ground, for the closing corner of Ts. 24 and 25 N.,

R. 48 $\frac{1}{2}$ E., with brass cap mkd:




1922

Dig pits, 18x18x12 ins., N., E. and S. of cor., 3 ft. distant.

40.00

78.00 Small spur, 140 ft. above draw, projects SW., continue along steep W. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for the cor. of secs. 25 and 36 only, with brass cap mkd:



1922

Dig pits, 18x18x12 ins., N., W. and S. of cor., 3 ft. distant.

40.2

47.6

Land, rolling and broken hilly. General W. drainage.

54.9

Soil, shallow gravelly loam, rocky subsoil, 3rd rate.

69.0

Undergrowth, sagebrush, buck brush, service berry.

75.2

Timber, juniper.

Good grazing.