

Dependent Resurvey of a portion of the 1st Standard Parallel South
thru
T. 4 S., R. 70 and 71 E.

Chains

79.60

The Std. cor. for secs. 32 and 33, which is a granite stone, 5 x 8 x 15 ins. set in mound of stone, marked and witnessed as described by the surveyor general; alongside of which

Set iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the Std. cor. of secs. 32 and 33, with brass cap marked

S C	
T 4 S	R 71 E
S 32	S 33

1922

from which

A pine, 6 ins. diam., bears $N.76\frac{1}{2}^{\circ}E.$, 70 lks. dist., mkd. T 4 S R 71 E S 33 B T.

A pine, 8 ins. in diam., bears $N.1^{\circ}W.$, 71 lks. dist., mkd. T 4 S R 71 E S 32 B T.

This cor. stands on SE. slope, 50 ft. below spur. Land, rough and mountainous, general drainage and exposure NW.

Soil, rocky and gravelly.

Timber, cedar, pinon and a few scattering yellow pine.

Undergrowth, oak, service berry, and sage brush.

Fair grazing.

$N.89^{\circ}53'E.$, on true line, on S. bdy. sec. 33.

Over broken SW. slope, covered with cedar and pinon timber, and undergrowth of sagebrush.

3.75

Point 40.00 chains westerly from NW. closing corners for sec. 4.

Set iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground, on solid rock, surrounded by mound of stone, for the $\frac{1}{4}$ sec. cor., for sec. 4 only, with brass cap marked

$\frac{1}{4}$ S 4
1922