

Survey of the subdivisions of T. 15 N., R. 50 E.

Chains.

48.20 Dry wash, drains N.

67.20 Dry wash, drains N.

80.10 The cor. of secs. 4, 5, 8 and 9.

Land, nearly level. Soil, gravelly clay. Undergrowth, dense black sage along bottom of washes and white sage over remainder of mile; very scant growth of grass. No timber.

N. 0° 03' W., bet. secs. 4 and 5.

Over slightly rolling land.

7.50 Dry wash, drains NE.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the 1/4 sec. cor., with brass cap mkd.

S5 | S4
1926

At base of post, deposit a granite stone, 8 x 6 x 4 ins. marked with cross (x). Pits impracticable and no other accessories available.

82.40 Intersect the Third Standard Parallel North, at a point, East, 5.99 chs. distant from the standard cor. of secs. 32 and 33. At the point of intersection, set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the closing cor. of secs. 4 and 5, with brass cap mkd.

T16N R50E
S33
S5 | S4
T15N R50E
C | C
1926

At base of post, deposit a granite stone, 10 x 8 x 6 ins., marked with cross (x). Pits impracticable and no other accessories available.

Land, slightly rolling. Soil, gravelly clay. Undergrowth, white sage; very scant growth of grass. No timber.