

South Boundary of T. 10 N., R. 51 E.

Chains

72.20 Road, bears N.30°W. and S.30°E. This is an old wood road leading to the Morey mining camp and apparently has not been used for many years.

80.00 On crest of small rocky spur projecting NE., 150 ft. above draw;

Set an iron post, 3 ft. long, 2 ins. diam., 8 ins. in the ground to solid rock and 20 ins. in a mound of stone 4 ft. base; for the cor. of secs. 5, 6, 31 and 32, with brass cap marked

T10N	R51E						
S 31	S 32						
<table style="border-collapse: collapse; margin: 0 auto;"> <tr> <td style="padding: 0 10px;">S 6</td> <td style="border-left: 1px solid black; padding: 0 10px;">S 5</td> </tr> <tr> <td colspan="2" style="text-align: center;">T 9 N</td> </tr> <tr> <td colspan="2" style="text-align: center;">1923</td> </tr> </table>		S 6	S 5	T 9 N		1923	
S 6	S 5						
T 9 N							
1923							

from which,

A pinon pine, 14 ins. diam., bears N.44°E., 72 lks. distant, marked T10N R51E S32 BT

A juniper, 5 ins. diam., bears S.27°E., 185 lks. distant, marked T9N R51E S5 BT

A juniper, 6 ins. diam., bears S.56½°W., 62 lks. distant, marked T9N R51E S6 BT

A pinon pine, 4 ins. diam., bears N.16½°W., 53 lks. distant, marked S31 BT

Land, rough and broken hilly and mountainous.

Soil, very shallow gravelly and rocky clay loam, coarse texture, rock subsoil, 3rd and 4th rate.

Undergrowth, sagebrush, buck brush, service berry, deer brush.

Timber, pinon pine, juniper, scattering clumps of heavy mahogany.

Good grazing.

West, on true line, bet. secs. 6 and 31,

Over rough and broken hilly and mountainous land thru heavy timber and medium dense undergrowth.

Desc. NW. slope.

6.70 Draw, drains NE., asc. SE. slope, along N. side of wash.