Independent Resurvey of the Third Standard Parallel North through Range 52 East

Chains

From this point the old standard corner, which is a pinon.post, 3 ft. long and 2 ins. square, marked 'SC T XVI N R LII E' on the N face, 'S XXXII on the E face and 'S XXXII on the W face, set in a mound of stone, bears N 79°15' W, 80 lks. dist.

I destroy all traces of this corner

Land, rolling hills, general NW exposure and drainage.

Soil, gravelly, 3rd rate.

Timber, juniper.

Undergrowth, sagebrush.

Poor grazing.

West on the S bdy. of sec. 31

Over rolling hills, through scattering timber and scant undergrowth, asc. 105 ft. over broken land to the standard  $\frac{1}{4}$  sec. cor.

15.40 Dry wash, drains NE.

40.00 Set an iron post, 3 ft. long and 1 in. in dia. 27 ins.

in the ground for the standard \( \frac{1}{4} \) sec. cor. of sec. 31

with a brass cap marked:

Deposit a granite stone, 10x8x6, marked with a cross

(X) at the base of the mounment. No trees available for marking and a mound of stone impracticable

No trace of the old standard corner found.

Asc. 170 ft. over broken land to corner.

66.40 Dry wash, drains NE.

77.40 Dry wash, drains NE.

80.00 On an E slope,

Set an iron post, 3 ft. long and 3 ins. in dia. 14 ins. in the ground and in a mound of stone for the Standard corner of Township 16 North, Ranges 51 and 52 East, with a brass cap marked: