

East Boundary of T. 10 N., R. 52 E.

Chains

the ground to bedrock, and supported by a mound of stone, for  $\frac{1}{4}$  sec. cor., with brass cap marked



from which

- A juniper, 6 ins. diam., bears N.  $76\frac{1}{2}^{\circ}$  W., 110 lks. dist., marked  $\frac{1}{4}$  S24 BT
- A juniper, 18 ins. diam., bears S.  $29\frac{3}{4}^{\circ}$  E., 197 lks. dist., marked  $\frac{1}{4}$  S19 BT

43.00 Wash, 5 ft. deep, 20 lks. wide, drains E.

60.70 Shallow wash, drains E.

61.50 Wash, drains SE.

79.00 Draw, SE.


80.00 On SW. slope,

Set an iron post, 3 ft. long, 2 ins. dia., 20 ins. in

the ground to bedrock and supported by a mound of

stone, for cor. of secs. 13, 18, 19 and 24, with

brass cap marked



1925

from which

- A juniper, 10 ins. diam., bears N.  $42\frac{1}{2}^{\circ}$  E., 126 lks. dist., marked T10N R53E S18 BT
- A juniper, 11 ins. diam., bears S.  $52^{\circ}$  E., 286 lks. dist., marked T10N R53E S19 BT
- A juniper, 18 ins. diam., bears S.  $19\frac{3}{4}^{\circ}$  W., 320 lks. dist., marked T10N R52E S24 BT
- A juniper, 30 ins. diam., bears N.  $64^{\circ}$  W., 407 lks. dist., marked T10N R52E S13 BT

Land, rolling and slightly broken with E. and SE. exposure and drainage.

Soil, gravelly and stony; 3rd rate.

Undergrowth, dense sagebrush.

Timber, very scattered juniper.

North, bet. secs. 13 and 18.

Over rolling and low broken land, through dense undergrowth and scattered timber; gently ascending.