

DEPENDENT RESURVEY OF A PORTION OF S. BDY  
T. 18 N., R. 54 E.

CHAINS	Set an iron post, 3 ft. long, 1 in. dia., on solid rock outcropping, over chiseled(x)cross, in a mound of stone, for $\frac{1}{2}$ sec. cor. of sec. 6 only, with brass cap mkd
	$\begin{array}{c} \frac{1}{2} S6 \\ 1924 \end{array}$
	Desc. precipitous rocky SW. slope 295 ft. to
50.30	Ravine, drains S. er.
51.40	Old road, bears N. and S.
	Asc. steep SE. slope 275 ft. to spur
72.00	Spur, projects S. Desc. 80 ft. to
159.18	Northing of 480.00 chs. from the cor. of Ts. 16 and 17 N., and Rs. 53 and 54 E., and westing of 159.02 from the cor. of secs. 4 and 5
	Set an iron post, 3 ft. long, 3 ins. dia., 20 ins. in the ground to solid rock, in a mound of stone, for the cor. of Ts. 17 and 18 N., Rs. 53 and 54 E., with brass cap mkd
	$\begin{array}{c} T18N \\ R53E \ R54E \\ \hline S36 \ S31 \\ \hline S1 \ S6 \\ \hline T17N \\ 1924 \end{array}$
	Land, rough mountainous. Soil, rocky.
	Timber, few pinon. Undergrowth, sagebrush and mountain rush.
	Poor grazing. General drainage, SE.

DEPENDENT RESURVEY OF A PORTION OF N. BDY  
T. 18 N., R. 54 E.

	Begin at the cor. of secs. 1, 2, 35 and 36, on N. bdy. of tp., which is a stone, marked and witnessed as described by the Surveyor General, alongside which
	Set an iron post, 3 ft. long, 2 ins. dia., 18 ins. in the ground to solid rock, in a mound of stone, with brass cap mkd
	$\begin{array}{c} T19N \ R54E \\ \hline S35 \ S36 \\ \hline S2 \ S1 \\ \hline T18N \\ 1924 \end{array}$
	At base of post deposit a marked stone, 1x2x3 ins.