

Completion of the survey of sec. 25, T. 30 N., R. 58 E.

Chains.

79.82 Intersect the cor. of secs. 25 and 26.

Land, rolling.

Soil, sandy to gravelly loam, 2nd and 3rd rate.

Undergrowth, sage, buckbrush.

Timber, scattering aspen.

Completion of the survey of sec. 24, T. 30 N., R. 58 E.

From the cor. of secs. 23 and 24,

N. $0^{\circ} 01'$ W., on a true line, bet. secs. 23 and 24.Asc. SE. slope 110 ft. over mountainous land, over
exposed granite ledges.

9.50 Dry wash, drains SW. Asc. 150 ft.

22.80 Dry wash, drains SE. Asc. SE. slope 440 ft.

40.00 On rocky E. slope set an iron post, 3 ft. long, 1 in.
in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor.,
with brass cap mkd.
$$\begin{array}{c} \frac{1}{4} \\ S23 | S24 \end{array}$$

1924

from which

A mahogany 10 ins. in diam., bears N. $13\frac{1}{4}^{\circ}$ W., 180 lks.distant, marked $\frac{1}{4}$ S23 BT
Sam Wine's house bears S. $9^{\circ} 35'$ E.
No other bearing trees available.

Asc. S. slope 70 ft.

44.10 Top of spur, projects SE. Desc. gradual NE. slope.

48.10 Head of a wash, drains E. Asc. rocky SE. slope 390 ft.

74.70 Top of spur, projects E. Desc. NE. slope 30 ft. through
dense undergrowth.80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 18 ins.
in the ground, to solid rock, in a mound of stone, for
the cor. of secs. 13, 14, 23 and 24, with brass cap mkd.
$$\begin{array}{c} T30N, R58E \\ S14 | S13 \\ S23 | S24 \\ 1924 \end{array}$$

from which