

## Survey of a portion of the subdivisions of T. 30 N., R. 58 E.

Chains.

- 44.60 Top of ridge, bears E. and W.
- 46.90 Desc. NE. slope 140 ft. through scattering mahogany and dense mountain laurel undergrowth, to dry wash.
- 55.00 Spring heads E. 4.00 chs. distant; water drains E.
- 58.10 Dry wash, drains E. Asc. SE. slope 70 ft. through dense mountain laurel.
- 63.50 Top of spur, projects E. Desc. NE. slope 190 ft. through dense undergrowth of laurel and buckbrush.
- 79.70 Creek with running water 6 lks. wide, 6 ins. deep, course SE.
- 79.75 Intersect the Sixth Standard Parallel North, at a point, West, 12.98 chs. distant from the Standard corner of secs. 35 and 36. Impracticable to set closing cor. at the point of intersection. At a point E., 30 lks. distant set an iron post, 3 ft. long, 2 ins. in diam., 30 ins. in the ground, for the <sup>witness</sup> closing cor. of secs. 1 and 2, with brass cap mkd.

T31N	R58E
W	S35
C	
S <sub>2</sub>	S <sub>1</sub>
T30N	R58E
C	C
	1924

from which

A cross marked on the NE. face of a granite boulder, bears S. 11° 45' W., 102 lks. distant, marked BO S1

A cross marked on the NE. face of a granite boulder, bears S. 7° 46' E., 80 lks. distant, marked BO S1

Land, rough mountainous.

Soil, shallow rocky clay loam, 3rd rate.

Undergrowth, sage, mountain laurel and buckbrush.

Timber, mahogany and aspen.

---