

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL
lines in T. 29 N., R. 59 E.

Chains

. 12, with brass cap marked

T29N	
R59E	R60E
S 1	S 6
S 12	S 7
1924	

Dig pits, 18x18x12 ins., in each sec., 3 ft. dist.

Land, slightly rolling.

Soil, sandy alkaline clay loam, medium texture, 3rd and
4th rate.

Undergrowth, sagebrush, shadscale, greasewood.

No timber. Poor grazing.

From the restored cor. of secs. 5, 6, 31 and 32, on the
S. bdy. of T. 29 N., R. 59 E., hereinbefore described,

N.1°26'E., on true line, bet. secs. 31 and 32,

Over level land thru very scattering rabbitbrush under-
growth and sparse grasses.

40.01 A northing of 40.00 chs. from the S. bdy. of the Twp.,
Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the
ground over a broken glass memorial, for the restored
 $\frac{1}{4}$ sec. cor., with brass cap marked

$\frac{1}{4}$	
S 31	S 32
1924	

Dig pits, 18x18x12 ins., N. and S. of post, 3 ft. dist.

80.02 A point 400.16 chs. ^{record} departure from the proportionate
point for the cor. of secs. 25, 30, 31 and 36 on the
E. bdy. of the Twp., and 80.00 ^{record} chs. latitude from the
cor. of secs. 5, 6, 31 and 32 on the S. bdy. of the Tp.
Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in
the ground over a broken glass memorial, for the re-
stored cor. of secs. 29, 30, 31 and 32, with brass cap
marked

T29N R59E	
S 30	S 29
S 31	S 32
1924	

Dig pits, 18x18x12 ins., in each sec., 3 ft. dist.

Land, level.