

Dependent Resurvey of the Boundaries of secs. 27, 34 and 35,

10

T. 22 N., R. 20 E.

Chains

43.80 Ravine, 105 ft. below $\frac{1}{4}$ sec. cor., course SW.; asc. 55 ft.
 48.15 Top of sharp rocky spur, projects S. 20° W.; desc. 100 ft.
 51.70 Top of nearly perpendicular bluff, 30 ft. high, facing W.;
 desc. 275 ft. to
 62.60 Head of gulch, course SW.; asc. 5 ft. to
 63.90 Point of rocky spur, projects S. 70° W.; desc. 30 ft. to
 65.45 Gulch, course N. 20° W.; asc. gradually.
 70.10 Point of low sandy spur, projects NW.; desc. 15 ft. to
 73.40 Gulch, course NW.; desc. 5 ft. to
 80.11 Intersect the cor. of secs. 33 and 34, which is a granite
 stone, 9x10x12 ins. above the ground, firmly set, mkd.
 and witnessed as described by the surveyor general. I
 reconstruct this cor., as follows: Alongside this cor.
 Set an iron post, 3 ft. long, 2 ins. dia., 27 ins. in the
 ground, for cor. of secs. 33 and 34, with brass cap mkd.

T22N | R20E

S33 | S34

S 3

T21N

1924

and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high,
 W. of cor.
 Land, mountainous.
 Soil, light sandy clay loam, medium texture, dry, shallow
 mixed with coarse gravel and decomposed limestone,
 and loose boulders; 4th rate.
 Undergrowth, sagebrush, buckbrush, peachbrush, greasewood,
 and a fair growth of various grasses.
 Timber, scattering scrub juniper.

From the reconstructed cor. of secs. 1, 2, 35 and 36, on
 the S. bdy. of the Tp.

N. 2° 05' E., on a true line, bet. secs. 35 and 36.

Over mountainous land, through dense undergrowth, desc.
 10 ft. to

8.70 Gulch, course S. 65° E.; asc. 30 ft. to
 30.00 Dry gravel gulch, course S. 75° E.;
 32.90 Dim road, bears N. 40° W. and S. 40° E.