

Survey of the East Boundary of T. 25 N., R. 45 E.

Chains
 44.50 Dry wash, course SE. Asc. S. slope 170 ft. to
 58.50 Top of spur, projects E. Desc. gradual N. slope.
 62.80 Dry wash, course S. 80° E.
 81.67 Top of spur, projects E. Desc. N. slope 70 ft. to
 84.47 Dry wash, course E. Asc. south talus slope 80 ft. to
 85.10 Intersect the 5th Standard Parallel North, at a point
 East, 4.30 chs., distant, from Std. $\frac{1}{4}$ sec. cor. sec. 36,
 which is an iron post, 1 in.
 in diam., firmly set and properly marked and witnessed
 as described in the field notes of T. 26 N., R. 45 E.
 At point of intersection, set an iron post, 3 ft. long,
 3 ins. in diam., 27 ins. in slide rock, accessories
 impracticable, for the closing corner of T. 25 N., R. 45
 & 46 E., with brass cap mkd.

T26N R45E	
S 36	
S1	S6
R45E	R46E
T25N	
CC	
1925	

Land, broken mountainous. Soil, rocky, gravelly, clay.
 Undergrowth, medium growth of sage and grass. No
 timber.

 Survey of the Subdivisions of T. 25 N., R. 45 E.

From the cor. of secs. 1, 2, 35 and 36, which is an iron
 post, 2 ins. in diam., firmly set and properly marked
 and witnessed as described in the field notes of T. 24
 N., R. 45 E.
 N. 0° 01' W., bet. secs. 35 and 36.
 Desc. N. slope 30 ft. to
 6.10 Dry wash, course N. 10° W.
 13.55 Dry wash, course N. 80° W.
 21.30 Draw, course N. 45° W.
 24.85 Top of ridge, bears N. 45° W. and N.W. and SE.
 Desc. NE. slope 35 ft. to
 32.55 Dry wash, course N. 45° W.
 35.90 Main wash, dry, course N. 80° W. Asc. SW. slope 95 ft. to