

Survey of the Subdivisions of T. 25 N., R. 45 E.

Chains

marked with cross (X) Other accessories impracticable.

51.20 Dry wash, course S. 30° E.

77.60 Road, bears NE. and SW.

84.76 Intersect the Fifth Standard Parallel North, at a point
E. 4.28 chs. distant from the Std. $\frac{1}{4}$ sec. cor. of sec.
31.

At point of intersection set an iron post, 3 ft. long,
2 ins. in diam., 27 ins. in the ground, for closing cor.
of secs. 5 and 6., with brass cap mkd.

T26NR45E
S31
S6 S5
T25NR45E
CC
1925

at base of post deposit a granite stone 5 x 4 x 4 ins.
marked with cross (X) Other accessories impracticable.

Land, nearly level. Soil, light, sandy, gravelly clay.

Undergrowth, sage, shadscale, rabbit brush and scant
growth of grass. No timber.

Latitudes, Departures and Closing Errors.

Line Designated.	Dist- ance.	Latitudes.		Departures	
		N.	S.	E.	W.
✓ E. Bdy.	---North---	485.10	485.10		
✓ N. Bdy.	---West---	477.48			477.48
✓ W. Bdy.	---South---	484.88	484.88		
✓ S. Bdy.	---N.89°59' E.---	477.64	.14	477.64	
Convergency	-----				.61
		485.24	484.88	477.64	478.09
		484.88			477.64
✓ Error in latitude	-----	.36			
✓ Error in departure	-----				.45