

Latitudes, Departures and Closing Errors, T. 26 N., R. 45 E.

Line Designated.	True Course	Distance.	Latitudes N.	S.	Departures E.	W.
East Bdy.	North		478.78			
North Bdy.	S. 89° 54' W.	44.37		.08		44.37
	N. 89° 36' W.	39.89	.28			39.89
	N. 89° 32' W.	40.24	.33			40.24
	N. 89° 09' W.	40.20	.59			40.20
	N. 89° 17' W.	39.83	.50			39.83
	N. 89° 19' W.	40.51	.48			40.51
	N. 89° 07' W.	39.56	.62			39.56
	West	194.42				194.42
West Bdy.	South	481.94		481.94		
South Bdy.	East	480.00			480.00	
	Convergency					.61
			481.58	482.02	480.00	479.63
				481.58	479.63	
	Error in latitude					.44
	Error in departure					.37

General Description, T. 26 N., R. 45 E.

The extreme southeast portion of this township, embracing secs. 25 and 36, the eastern portion of secs. 24, 26 and 35, is broken and rough mountainous land, descending abruptly to slightly rolling land in the central portion of the township. The land in the western portion ranges from broken mountainous to rolling mountainous land, and descends gradually to nearly level land in the central portion of the township. All of the land within the township can be utilized for grazing purposes.

The soil of the higher land is a light, sandy, gravelly and rocky clay, and that of the lower land is a heavy, gravelly clay containing much alkaline.

Caraco Lake situated in the central portion of the township, is a dry lake bed, the soil of which is a heavy alkaline clay devoid of vegetation.

There is a warm spring located in sec. 16, from which a small stream of water flows through the NE $\frac{1}{4}$ of the section. to the dry bed of Caraco Lake. This water is suitable for stock watering purposes. There are small springs located in the NE $\frac{1}{4}$ sec. 15, NW $\frac{1}{4}$ sec. 11 and the SE $\frac{1}{4}$, sec. 34 of this township.

28, 29 and J.C. Wholey, located in secs. 32, was the only settler residing within the township at the time of this survey.