

Survey of the subdivisions of T. 27 N., R. 46 E.

Chains.

Land, nearly level. Soil, light, sandy, gravelly and rocky clay. Undergrowth, sage, shadscale and scant growth of grass.

Latitudes, Departures and Closing Errors.

Line Designated	True Bearing	Distance	Latitudes		Departures	
			N.	S.	E.	W.
E. Bdy.	North	496.00	496.00			
N. Bdy.	N. 89° 54' W.	239.66	.42		239.66	
	N. 89° 48' W.	80.60	.28		80.60	
	N. 89° 50' W.	154.04	.45		154.04	
	N. 89° 55' W.	42.56	.06		42.56	
	South	17.74		17.74		
W. Bdy.	S. 3° 08' W.	78.58		78.47		4.29
	S. 0° 27' W.	40.76		40.76		.32
	S. 0° 37' W.	40.06		40.06		.43
	S. 0° 37' W.	40.42		40.42		.43
	S. 0° 23' E.	40.40		40.40		.27
	S. 0° 27' W.	40.18		40.18		.31
	S. 0° 17' W.	40.22		40.22		.20
	S. 0° 11' W.	40.36		40.36		.13
	S. 0° 12' E.	40.18		40.18		.14
	S. 0° 22' W.	39.95		39.95		.26
	S. 0° 11' W.	40.08		40.08		.13
S. Bdy.	N. 89° 54' E.	523.43	.91		523.43	
	Convergency					.66
			498.12	498.82	523.84	524.02
			498.12			523.84
	Error in latitude			.70		
	Error in departure				.66	.18

General Description of T. 27 N., R. 46 E.

The greater portion of the land in this township is nearly level or slightly rolling. The north central portion of the township is rolling and broken. A ridge traverses the township in a northerly and southerly direction through sections 32, 33 and 28, and one in a northerly and southerly direction through sections 35 and 36. These ridges are rocky, broken and mountainous with sparse vegetation. The slopes on either side descend abruptly to slightly rolling or nearly level land. The extreme northwest portion of the township is rough, rocky and broken mountainous. The entire area of the township