

## Dependent Resurvey of the E. Bdy. of T. 46 N., R. 33 E.

Chains.

for the cor. of Ts. 46 and 47 N., R. 33 E., with brass cap mkd.

T47N	
R33E	T47N
S36	R34E
S1	S31
T46N	
	1923

Raise a mound of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of the cor.

Land, rolling. Soil, sandy and rocky clay loam with rocky subsoil. Undergrowth, medium growth of sage and scattering grass. Poor grazing. *Std*

Retracement of the 9th Std. Par. N., through a portion of R. 34 E.

From the Std. cor. of T. 46 N., Rs. 33 and 34 E., hereinbefore described.

East, on retracement, on the S. Bdy. of sec. 31.

6.46 Fall 11 lks. N. of the closing cor. of T. 45 N., Rs. 33 and 34 E., which is a decayed cottonwood post, 2 ft. long, 2 ins. in diam., with markings obliterated, set in a mound of earth.

39.95 Fall 69 lks. N. of the Std.  $\frac{1}{4}$  sec. cor., which is a decayed cottonwood post, 24 ins. long, 2 ins. in diam., lying on a mound of earth. No evidence of markings.

The course of this  $\frac{1}{2}$  mile is S.  $89^{\circ} 01'$  E. and the dist. is 39.96 chs.

80.12 Fall 121 lks. N. of the Std. cor. of secs. 31 and 32, which is a decayed cottonwood post, 20 ins. long, 2 ins. in diam., lying on a mound of earth, marked XXX11 on one face. No other markings distinguishable. The course of the E.  $\frac{1}{2}$  mile is S.  $89^{\circ} 15'$  E. and the dist. is 40.18 chs.

From the Std. cor. of secs. 31 and 32,

East, on retracement, on the S. Bdy. of sec. 32.