


SURVEY OF W. BOUNDARY T. 28 N., R. 27 E.


Chains North, between secs. 1 and 6.
 20.00 Over mountainous to rough mountainous land.
 Asc. sandy SE. slope 105 ft. to
 19.95 Asc. rocky and sandy steep SE. slope 610 ft. to 71.40
 40.00 Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the
 ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd



No stone available for mound; pits impracticable.

At base of post deposit a mkd(X) granite stone, 4x4x4 ins.
 60.20 Ravine, drains S. 40° E.
 71.40 Rocky spur, projects E.

Desc. steep rocky NE. slope 95 ft. to
 80.00 Set an iron post, 3 ft. long, 3 ins. dia., 20 ins. in
 the ground to solid rock, in a mound of stone, for the
 cor. of Ts. 28 and 29 N., Rs. 26 and 27 E., with brass
 cap mkd



At base of post deposit a mkd(X) granite stone, 6x6x4 ins.
 Land, mountainous and rough mountainous.
 Soil, coarse loose sand intermixed with small rock and
 decomposed granite.
 Timber, none. Undergrowth, sage, greasewood.
 General drainage, E. Grazing, poor.

SURVEY OF A PORTION OF E. BOUNDARY T. 28 N., R. 27 E.

I begin at the cor. of secs. 25, 30, 31, and 36, on E.
 boundary of township, which is a basalt stone, firmly
 set in the ground, marked with 1 notch on S. face, and
 5 notches on N. face, with mound of stone W. of cor.
 Thence