

Independent Resurvey

Sixth Standard Parallel North, through Range 28 East

Chains	No suitable trees within limits
	At base of post deposit a marked (X) granite stone, 6x7x8 ins.
44.95	Spur, projects N. 85° W. Desc. SW. slope 170 ft. to
54.45	Main ravine, wash, 20 lks. wide, 1 ft. deep, drains
	N. 70° W. Asc. NE. slope 150 ft. to
57.25	Desc. NW. slope 70 ft. to
64.70	Ravine, drains N., heads about 7 chs. S.
	Asc. steep NE. slope 135 ft. to
70.90	Desc. NW. slope 30 ft. to
72.80	Ravine, drains N., heads about 2 chs. S.
	Asc. NE. slope 35 ft. to
74.30	Spur, projects N. about 3 chs., thence NW.
	Desc. NW. slope 45 ft. to
80.00	Find no trace of old standard sec. cor.
	Set an iron post, 3 ft. long, 2 ins. dia., 8 ins. in the
	ground to solid rock, in a mound of stone, for the
	standard cor. of secs. 31 and 32, with brass cap mkd
	SC T31N R28E
	S31   S32
	1927
	No suitable trees within limits
	At base of post deposit a mkd (X) granite stone, 2x6x8 ins.
	Land, rough mountainous. Soil, rocky and gravelly.
	Timber, scattering juniper. Undergrowth, sage, shadscale.
	General drainage, NW. Grazing, fair.
	West, through sec. 31
	Over rough mountainous land
	Desc. SW. slope 195 ft. to ravine
.78	Point for closing cor. of secs. 5 and 6
7.75	Ravine, drains N. 45° W.
	Asc. steep NE. slope 105 ft. to
12.90	Spur, projects N. Desc. NW. slope 35 ft. to
16.00	Head of ravine, drains N. Asc. NE. slope 75 ft. to
21.20	Spur, projects N. 25° W.
	Desc. W. to NW. slope 210 ft. to spur