

Survey of S. Boundary T. 32 N., R. 28 E.

Chains

80.00

Set an iron post, 3 ft. long, 2 ins. dia., 27 ins. in the ground, for the cor. of secs. 5, 6, 31 and 32, with brass cap mkd

T32N	R28E
S31	S32
<hr/>	
S6	S5
<hr/>	
T31N	
1927	

No stone available; pits impracticable.

At base of post deposit a marked(X) stone, 2x3x4 ins.

Land, gently rolling. Soil, sandy gravelly loam.

Timber, none. Undergrowth, sagebrush, shadscale, buckbrush.

General drainage, NW. Grazing, poor.

40.00

West between secs. 6 and 31

Over rolling land. General descent of 40 ft. to twp. cor.

Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd

S 31
$\frac{1}{4}$
S 6
1927

No stone available.

Digs two pits crosswise on line, E. and W. of cor.

75.60

Wash in draw, 15 lks. wide, 1 $\frac{1}{2}$ ft. deep, drains N.

79.38

Set an iron post, 3 ft. long, 3 ins. dia., 27 ins. in the ground, for the cor. of Ts. 31 and 32 N., Rs. 27 and 28 E., with brass cap mkd

T32N	
R27E	R28E
S36	S31
<hr/>	
S1	S6
<hr/>	
T31N	
1927	

No stone available.

Dig four pits, N, E, S and W. of cor.

Land, rolling. Soil, gravelly.

Timber, none. Undergrowth, sagebrush, shadscale.

To her 211