

Subdivisions T. 31 N., R. 29 E.

Chains	
80.12	The cor. of secs. 3, 4, 9, and 10 Land, rolling mountainous. Soil, rocky and gravelly. Timber, none. Undergrowth, sagebrush, shadscale. General drainage, NE. Grazing, fair.
40.00	N. $0^{\circ} 09'$ W., on a random line between secs. 3 and 4 Set temp. $\frac{1}{4}$ sec. cor.
81.28	Intersect N. boundary of township 29 lks. W. of the cor. of secs. 33 and 34, T. 32 N., R. 29 E., which is a 2 in. iron post, firmly set in the ground and a mound of stone, marked and witnessed, as described in the original field notes. I remark same to read as follows:
	T32NR29E S33 S34 S4 S3 T31N 1927
	Thence ✓
	S. $0^{\circ} 03'$ W., on true line between secs. 3 and 4 Over rough mountainous land. Desc. steep rocky SE. slope 165 ft. to
12.25	Wash and old road, bears N. 70° E. and S. 70° W., drains NE. Asc. rocky NE. slope 255 ft. to 22.45
19.25	Spur, projects N. 65° E. NE. cor. of Joe Richardson house bears S. $80^{\circ} 21'$ W., 32.42 chs.
22.45	Desc. SE. slope 80 ft. to
31.85	Ravine, drains E. Asc. NE. slope 60 ft. to
34.25	Spur, projects E. Desc. steep SE. slope 150 ft. to wash
41.28	On rocky SE. slope Set an iron post, 3 ft. long, 1 in. dia., 18 ins. in rocky ground, in a mound of stone, for the $\frac{1}{4}$ sec. cor., with brass cap mkd
	$\frac{1}{4}$ S4 S3 1927
	At base of post deposit a marked(X)stone, 2x4x6 ins.