

Subdivisions T. 28 N., R. 54 E.

Chains	Timber, none. Undergrowth, sagebrush. General drainage, E. Grazing, poor.
	East, on a random line bet. secs. 3 and 10
40.00	Set temp. $\frac{1}{4}$ sec. cor.
79.76	Fall 16 lks. N. of the cor. of secs. 2, 3, 10 and 11 Thence N. $89^{\circ} 53'$ W., on true line bet. secs. 3 and 10 Over practically level land
16.40	Road, bears NE. and SW.
39.88	Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd $\begin{array}{c} S 3 \\ \frac{1}{4} \\ S 10 \\ 1926 \end{array}$
79.76	Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor. The cor. of secs. 3, 4, 9 and 10 Land, rolling bench. Soil, gravelly clay. Timber, none. Undergrowth, sagebrush. General drainage, E.. Grazing, poor.
40.00	N. $0^{\circ} 02'$ W., on a random line bet. secs. 3 and 4 Set temp. $\frac{1}{4}$ sec. cor.
79.28	Intersect N. bdy. of twp. 33 lks. E. of the cor. of secs. 33 and 34, T. 29 N., R. 54 E., which is a 2 in. iron post, firmly set in the ground, properly mkd. and witnessed as described in the field notes of the survey of T. 29 N. R. 54 E., under Group No. 94. I change markings to read as follows: $\begin{array}{c} T29NR54E \\ S33 \quad S34 \\ \hline S4 \quad S3 \\ T28NR54E \\ 1926 \end{array}$
	Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor. Thence S. $0^{\circ} 16'$ E., on true line bet. secs. 3 and 4 Over gently rolling land. General descent of gentle S.