

Survey of a portion of the subdivisions of T.28 N., R.41 E.

Chains.

56.60 Dry wash, drains NW.

58.30 Dry wash, drains NW.

78.06 Intersect the W. Bdy. of the township, at a point,
North, 4.49 chs. distant from the cor. of secs. 13 and
24, which is an iron post, 2 ins. in diam., firmly set
and properly marked and witnessed as described in the
field notes of T. 28 N., R. 40 E.

At the point of intersection, set an iron post, 3 ft.
long, 2 ins. in diam., 27 ins. in the ground, for the
closing cor. of secs. 18 and 19, with brass cap mkd.

	T28N	
T28N	S18	C
R40E	S19	C
S13	R41E	
1926		

Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of
the cor.

Land, slightly rolling. Soil, light, sandy, gravelly and
rocky clay. Undergrowth, sage in bottom of washes and
medium growth of shadscale. Sparse growth of grass.
No timber.

Note: The old cor. of secs. 13, 18, 19 and 24, reestablish-
ed with an iron post under surveys in T. 28 N., R. 40 E.,
for the cor. of secs. 18 and 19 was destroyed.

From the $\frac{1}{4}$ sec. cor. for sec. 24 on the E. Bdy. of
T. 28 N., R. 40 E., which is an iron post, 1 in. in
diam., firmly set and properly marked and witnessed as
described in the field notes of T. 28 N., R. 40 E.,
North on a true line.

4.435 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins.
in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 19, only,
with brass cap mkd.

	$\frac{1}{4}$
S19	
1926	

Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of
the cor.