

Survey of the S. Bdy. of T. 23 N., R. 46 E.

Chains.

Land, rolling. Soil, light, sandy and rocky clay.

Undergrowth, shadscale, sage and scant growth of grass.

No timber.

East, on a true line, on the S. Bdy. of sec. 36.

Desc. gradual NE. slope over slightly rolling land.

22.10 Road, bears N. 20° W. and S. 20° E.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins.
in the ground, for the $\frac{1}{4}$ sec. cor. for sec. 36, with
brass cap mkd.

$\frac{1}{4}$ S36

1925

Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of
the cor.

61.50 Dry wash, course SE.

80.00 A point 8.38 chs. N. of the old cor. of Ts. 22 and 23 N.,
Rs. 46 and 47 E., hereinbefore described.

Set an iron post, 3 ft. long, 3 ins. in diam., 27 ins.

in the ground, for the closing cor. of Ts. 22 and 23 N.,
R. 46 E., with brass cap mkd.

	T23N	
	R46E	T23N
C	S36	R47E
C	S1	S31
	T22N	
	1925	

At base of post, deposit a granite stone, 8 x 7 x 5 ins.,
marked with cross (x). No other accessories available.

Land, slightly rolling. Soil, light, sandy and gravelly
clay. Undergrowth, medium growth of shadscale, scatter-
ing growth of sage and scant growth of grass.

No timber.