

Independent Resurvey of the E. Bdy. of T. 23 N., R. 46 E.

Chains.

Land, nearly level with gradual SE. drainage. Soil, light, sandy, gravelly clay. Undergrowth, medium growth of shadscale, scattering growth of sage and scant growth of grass. No timber.

North, on a true line, on the E. Bdy. of sec. 12.

Asc. gradual SE. slope over nearly level land.

10.00 Dry wash, course SE.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor. for sec. 12, with brass cap mkd.

$\frac{1}{4}$
S12
1925

At base of post, deposit a granite stone, 8 x 6 x 4 ins., marked with cross (x). No other accessories available.

50.00 Slope changes to NE. Desc. gradually.

60.00 Dry wash, course SE.

77.00 Dry wash, course SE.

80.00 Set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the cor. of secs. 1 and 12, with brass cap mkd.

T23N
S1
S12
R46E
1925

At base of post, deposit a granite stone, 4 x 8 x 12 ins., marked with cross (x). No other accessories available.

Land, nearly level. Soil, light, sandy, gravelly and rocky clay. Undergrowth, medium growth of shadscale, scattering growth of sage and scant growth of grass. No timber.

North, on a true line, on the E. Bdy. of sec. 1.

Desc. gradual NE. slope over nearly level land.

10.00 Dry wash, course SE.

38.50 Dry wash, course SE.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins.