

DEPENDENT. RESURVEY. EAST BOUNDARY OF T. 37 N., R. 48 E.

Chains

corners found. These corners were reconstructed by placing the regulation iron posts alongside the original monuments. All missing section corners were restored by double proportionate measurement and the missing quarter section corners were restored by single proportionate measurement on line between the section corners.

DEPENDENT RESURVEY EAST BOUNDARY OF T. 37 N., R. 48 E.

REESTABLISHMENT OF SURVEYS EXECUTED BY HATCH, EATON AND SMYLES, U.S. DEPUTY SURVEYORS IN 1872.

Random Lines.


For record of the random line along E. bdy. of T. 37 N., R. 48 E., see the field notes of the dependent resurvey of T. 38 N., R. 48 E., this group.

True Lines.

The original cor. of Ts. 36 and 37 N., Rs. 48 and 49 E., is a decayed hewed willow stake, 3 ft. long, 2 ins. sq., lying on old deeply embedded mound of stone. All traces of marks have decayed off stake.

In center of old mound of stone.

Set an iron post, 3 ft. long, 3 ins. diam., 28 ins. in the ground for cor. of Ts. 36 and 37 N., Rs. 48 and 49 E., with brass cap marked



Set old willow stake alongside of iron post, and raise a mound of stone, 2 ft. base, 1½ ft. high S. of cor.

Thence