

3
Independent Resurvey of Second Standard Parallel North
Through Range 29 East
T. 11 N., R. 29 E.

Chains	
63.20	Ridge, bears N. 45° W. and S. 45° E.
	Desc. steep rocky NE. slope 320 ft. to
80.00	Find no trace of old standard sec. cor.
	Set an iron post, 3 ft. long, 2 ins. dia., 6 ins. in the
	ground to solid rock, in a mound of stone, for the stand-
	ard cor. of secs. 31 and 32, with brass cap mkd
	SC T11NR29E S31/S32 1929
	At base of post deposit a mkd(X) granite stone, 4x6x6 ins.
	Land, rough mountainous. Soil, rocky with decomposed
	granite, numerous ledges. Timber, none. Undergrowth,
	sage, shadscale. General drainage, SE. Grazing poor.
	DEPENDENT RESURVEY OF PORTION OF NORTH BOUNDARY T. 11 N., R. 29 E. REESTABLISHMENT OF SURVEYS EXECUTED BY FRANKS AND MULLEN, U.S. DEPUTY SURVEYORS, UNDER CONTRACT NO. 237, IN 1904.
	Random Lines.
	From the $\frac{1}{4}$ sec. cor. between secs. 31 and 36, T. 12 N.,
	Rs. 28 and 29 E., which is a granite stone, firmly set
	in the ground, and marked and witnessed as described
	in the official records of the survey of T. 12 N., R. 28 E.
	South, between secs. 31 and 36
40.00	Find no trace of old cor. of Ts. 11 and 12 N., Rs. 28
	and 29 E. Set temporary point
	From the cor. of secs. 1, 2, 35 and 36, Ts. 11 and 12 N.,
	R. 28 E., which is a lava stone, firmly set in the
	ground, and marked and witnessed as described in the
	official records of the survey of T. 12 N., R. 28 E.
	East, along S. boundary of sec. 36
40.00	Find no trace of old $\frac{1}{4}$ sec. cor.
80.00	Find no trace of old township cor.
80.61	Fall 3 lks. N. of temporary point for Ts. 11 and 12 N.,
	Rs. 28 and 29 E., hereinbefore mentioned