

Dependent Resurvey of Portion of North Boundary

T. 11 N., R. 29 E.

Chains Hawthorne

28.35 Wash, 10 lks. wide, 3 ft. deep, drains S. 50° E.

40.23 The old $\frac{1}{4}$ sec. cor., which is a granite stone, firmly set in the ground, and marked and witnessed as described in the official records of the survey of T. 12 N., R. 29 E. This corner now becomes the $\frac{1}{4}$ sec. cor. of sec. 31 only

Land, rolling. Soil, gravelly loam.

Timber, none. Undergrowth, sage, buckbrush.

General drainage, E. Grazing, poor.

SURVEY OF PORTION OF NORTH BOUNDARY T. 11 N., R. 29 E.

From the $\frac{1}{4}$ sec. cor. of sec. 31

East, along N. boundary of sec. 6

Over gently rolling land

Gentle descent

.36 Find no trace of old meander corner

4.73 Easting of 40.00 chs. from the closing cor. of Ts. 11 N., Rs. 28 and 29 E., hereinafter described

Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 6 only, with brass cap mkd

$\frac{1}{4}$ S6

1929

Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, S. of cor.

8.35 Mean high-water mark of Walker Lake

Set an iron post, 3 ft. long, 2 ins. dia., 27 ins. in the ground, for the meander cor. of sec. 6, with brass cap mkd

T12N

S6

T11N R29E

1929

MC

Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.

Land, gently rolling to level. Soil, gravelly sand.

Timber, none. Undergrowth, none.

General drainage, E. Grazing, none.